



APPLICATION CASE STUDY:

Project Description: Apply Product to Outdoor Signage
Customer: Fifth Third Bank
Location: Cincinnati, Ohio
Date: July, 2016

PROJECT DETAILS

Project Overview:

Fifth Third has many forms of signage and much of it was starting to oxidize and showed signs of bacteria growth. Their approach was to research cleaning methods only until X-RESTORE was proposed as a restoration and protective solution. The signs cleaned up easily and the application process provided the look and curb appeal that was desired.

xGen Product Purchased Through:

Wuchterl Associates, Cincinnati

Customer Contact:

Jim Schwarz, Viox Services

PRODUCT DETAILS

xGen Product Utilized:

X-RESTORE Oxidized Metal

Features & Benefits:

The X-RESTORE Oxidized Metal coating provided a beautiful, glossy, "like new" finish to the customer's signage. X-RESTORE will protect the fixtures from future oxidation and protect from UV fading. The signage will be easy to keep clean and will retain a glossy, "like-new" look for 5-7 years. The Customer is extremely pleased with gloss and appearance of their signage.



BEFORE & AFTER APPLICATION